

OIL ALERT SENSOR

Oil
Alert



Sensor Replaces Honda 34150-ZH7-023 Honda code 5858444 Honda code 5858444 Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly, Use with 120-430 Oil Switch Assembly 120-430 Oil Switch Assembly

Honda code 5858444 Honda code 5858444

Ariens DelerStens Deler

GTIN	2.3899262687E10
Produktgrupp	Oil Alert Sensor
Antal per artikel	1 stk
Vikt	0.022679618500000002 kg
OEM-nr	Honda 34150-ZH7-003, 34150-ZH7-013, 34150-ZH7-023;
Passar modell	Honda GX120, GX160, GX200, GX240, GX270, GX340 and GX390
Ingår i	Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly, Use with 120-430 Oil Switch Assembly 120-430 Oil Switch Assembly
Ytterligare info	Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly, Use with 120-430 Oil Switch Assembly 120-430 Oil Switch Assembly
GTIN	2.3899262687E10
Competitors	286-9173 33-542 7-01983
Cross Sell	120-101, 120-430
Up Sell	Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly, Use with 120-430 Oil Switch Assembly 120-430 Oil Switch Assembly

Läs mer om produkten här:

<https://www.ariens.se/product?number=120-434>