

OIL SWITCH ASSEMBLY

Produkt



Switch Assembly Replaces Honda 15510-ZE2-053 Honda code 5792361-5361605-8755167 Honda code 5792361-5361605-8755167 Use with 120-434 Oil Alert Sensor 120-434 Oil Alert Sensor, Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly

Honda code 5792361-5361605-8755167 Honda code 5792361-5361605-8755167

Ariens DelerStens Deler

GTIN	2.3899249664E10
Produktgrupp	Oil Switch Assembly
Antal per artikel	1 stk
Vikt	0.0544310844 kg
OEM-nr	Honda 15510-ZE2-033, 15510-ZE2-043, 15510-ZE2-053;
Passar modell	Honda GX240, GX270, GX340 and GX390
Ingår i	Use with 120-434 Oil Alert Sensor 120-434 Oil Alert Sensor, Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly
Ytterligare info	Use with 120-434 Oil Alert Sensor 120-434 Oil Alert Sensor, Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly
GTIN	2.3899249664E10
Competitors	030-967 33-21 7-01979 FF-0430
Cross Sell	120-434, 120-101
Up Sell	Use with 120-434 Oil Alert Sensor 120-434 Oil Alert Sensor, Use with 120-101 Oil Switch Assembly 120-101 Oil Switch Assembly

Läs mer om produkten här:

<https://www.ariens.se/product?number=120-430>