

OIL SWITCH ASSEMBLY

Produkt



Switch Assembly Replaces Honda 15510-ZE1-043 Honda code 5962063-1501733-5262605-8755159 Honda code 5962063-1501733-5262605-8755159 Use with 120-434 Oil Alert Sensor 120-434 Oil Alert Sensor, Use with 120-430 Oil Switch Assembly 120-430 Oil Switch Assembly

Honda code 5962063-1501733-5262605-8755159 Honda code 5962063-1501733-5262605-8755159

Stens Deler

Produktgrupp	Oil Switch Assembly
Antal per artikel	1 stk
Vikt	0.040823313300000004 kg
OEM-nr	Honda 15510-ZE1-003, 15510-ZE1-013, 15510-ZE1-023, 15510-ZE1-033, 15510-ZE1-043;
Competitors	2444 33-540 33-541 7-01978 FF-1010
Passar modell	Honda GX110, GX120, GX160 and GX200
Cross Sell	120-434, 120-430
Up Sell	Use with 120-434 Oil Alert Sensor 120-434 Oil Alert Sensor, Use with 120-430 Oil Switch Assembly 120-430 Oil Switch Assembly
Ytterligare info	Use with 120-434 Oil Alert Sensor 120-434 Oil Alert Sensor, Use with 120-430 Oil Switch Assembly 120-430 Oil Switch Assembly

Läs mer om produkten här:

<https://www.ariens.se/product?number=120-101>